We have seen an issue where sometimes the USB dongle is not correctly recognized and the Amulet software runs in a limited evaluation mode. Users who experience this problem should email support@amuletdevices.com to resolve the issue.

Known issue with software version 2.17.50

Forum discussion